



**m/v Valbella – Cement vessels – Colombo July 2007
Repairs and dry docking specification.**



**m/t Clipper Kristin – Chemical tanker – Astican Las Palmas August 2007
Dry docking and steel repair.**




**m/v Elbia – Cement vessel – Maceió Brazil October 2007
Repairs and DD specification**



**4. Clipper Karen – Chemical tanker - Nov 2007 Frederica Shipyard
Dry docking, installation of inert gas system and stern manifold.**



**M/tr Hercules – Fishing stern trawler – November 2007 Talcahuano Chile.
Engine room inspection after fire**



**m/t Clipper Tobago – Chemical tanker – Houston November 2007
Supervision of SS tank repair.**

